

StarFire™ 6000 Receiver

Software Update 19-2 Release Notes

4.20K

Resolved Items:

StarFire™ 6000 Not Populating on VT – When machine key switch is turned on, but engine is off, StarFire™ 6000 populates on the display VT. Then when the engine is started, the StarFire™ 6000 no longer loads on the VT. This issue has been resolved with 4.20K.

Release Notice

These are software release notes for the StarFire™ 6000. Release Notes can be found on www.stellarsupport.com. Note: Your use of the software is governed by the End User License Agreement included with the software.

Copyright © 1996-2019 Deere & Company