

# StarFire™ 6000 Receiver

Software Update 19-2 Release Notes  
4.20N

---

## Resolved Items:

**StarFire 6000 fails reprogramming** – When updating from 4.20K using a CAN reprogramming method, StarFire 6000 fails reprogramming. Software version 4.20N resolves this issue.

**StarFire™ 6000 Not Populating on VT** – When machine key switch is turned on, but engine is off, StarFire™ 6000 populates on the display VT. Then when the engine is started, the StarFire™ 6000 no longer loads on the VT. This issue has been resolved with 4.20K.

---

## Release Notice

These are software release notes for the StarFire™ 6000. Release Notes can be found on [www.stellarsupport.com](http://www.stellarsupport.com). Note: Your use of the software is governed by the End User License Agreement included with the software.

**Copyright © 1996-2019 Deere & Company**