HarvestLab™ Software Update V144 Release Notes

Important Notes:

This software is updating your HarvestLab™ 3000 sensor to version V144.

To perform the software update, please download the software bundle from StellarSupport™ at HarvestLab™ section. To connect the HarvestLab™ 3000 sensor with your laptop, you must use an Ethernet cable (PFP16262: Ethernet Cable (M12 to RJ45)). Please follow the steps on HarvestLab™ web UI to update the software. (https://www.youtube.com/watch?v=atQQGueHYJY&feature=youtu.be)

Release Notes:

Date	Software	Version
June 2022	John Deere Harvestlab™ 3000 sensor	V144

V144

- Improved external reference process
- Increase of sensor performance
- Software update process improved
- Bug fixing

Note: A refresh of the browser is needed after installation of software update.