

Resolved Issues

The following issues are fixed in software update 10.16.1400-85:

General (May Apply to Multiple Field Operations)

- Operator may be unable to close out the Help Center application after opening it until display is rebooted
- Display may encounter an “Application Unexpectedly Quit” error if the operator changes track spacing while recording an adaptive curve

Cotton Harvesting

- Operator may be unable to enable AutoTrac™ RowSense™ on CP690 or CS690 cotton harvesters after the display completed a warm boot

Release Notice

These are Generation 4 OS and AMS Applications software update release notes for the Generation 4 Displays. Release notes can be found on www.stellarsupport.com. Note: Your use of the software is governed by the End User License Agreement included with the software.

Copyright © 1996-2020 Deere & Company